




These release notes contain information regarding new functionalities, behaviors, changes, and other new experiences you should expect when using this latest version of the product.

Legend







Information: General information needed to understand the context, behaviors, and restrictions associated with new enhancements and corrections.



v3.0.70 (8/18/2021)

Enhancements

The following items are newly-implemented features intended to increase end-user productivity throughout TrackIt.



Begin Loading and Loaded statuses sent from

(CA-514)

Probe

For COMMANDassurance customers, the *Begin Loading* and *Loaded* statuses can now be triggered by the Probe. This is a secondary function that will assist in the event that the status change sent from the batching system does not reach TrackIt. If that occurs, the Probe will detect when the drum is getting loaded and when loading is complete.



The Probe firmware must be updated to version 4.43.1.0 or higher to utilize this feature.

Corrections

The following tickets are improvements upon unexpected user experiences for a more fluid and productive experience throughout TrackIt.



Time zone corrections in System Health

(FEL-4763)

Corrected behavior:

The timezone in System Health reports now displays based on the site's current configuration.

Previous behavior:

The timezone in System Health reports was always displaying in Mountain Time.





Corrected Employee Number on Trip Summary

(FEL-4788)

Corrected behavior:

The correct value is now returned in the **Employee Number** field on the Trip Summary report.

Previous behavior:

Previously, the **Employee Number** field on the Trip Summary report was always returning *-1*.

